



www.omnisite.com • 203 West Morris Street Indianapolis, IN 46225

YOUR OMNI HAS BEEN TUNED UP!

Schedule your Total Tune 20

See back for package details >



What's on the Total Tune 20 Tune-Up Checklist?

- Clean the product inside.
- Clean the product outside.
- Replace missing screws.
- Provide free return shipping.
- Replace the primary battery (applicable to each OmniSite product).
- Upgrade the primary battery bracket to a quick removal type.
- Replace the secondary timeclock battery.
- Upgrade firmware in the primary circuit board to the latest version.
- Upgrade firmware in the radio carrier circuit board to the latest version.
- Upgrade firmware in the cellular radio to the latest version.
- Upgrade the radio to 4G technology if needed.
- Upgrade the antenna and coax cable for 4G service as needed.
- Perform a radio signal strength test.
- Test all digital inputs.
- Test all analog inputs.
- Validate that the GuardDog interface is correctly configured.
- Validate that product internal settings are optimized for the customer's application.

- Verify that customer contact and notification lists are correct and not out of date.
- Update product manufacturing records.
- Apply a new 1-year warranty to the product in the OmniSite FUSION record management system.

SCHEDULE TODAY

Email

support@omnisite.com for

an RMA or call

317-885-6330 x3



Crystal Ball



XR50



OmniBeacon



GuardDog